

Original BMW Accessories. Installation Instructions.



Alarm Kit

BMW 1 Series Coupe (E82), Select Vehicle Production 12/07 - On

Vehicle must have optional alarm pre-wiring (SA 5GA), which is 100% option for US spec vehicles.

Retrofit kit No. 65 73 0 444 089

Installation time

The installation time is 1.0 hours, but this may vary depending on the condition of the car and the equipment in it.

Suggested installation time includes re-coding of the vehicle only for this retrofit kit. This time is based on a vehicle that is at the current software level and does not require any updates. Before installing this accessory into the vehicle, the vehicle should be connected to the DIS and checked for software updates. If updates are available the vehicle should be programmed prior to installing this accessory.

If vehicle is under warranty, the costs of programming prior to retrofit should use defect code 72 60 93 02 00.

Please refer to SI B09 05 01 for latest BMW approved CIP Retrofit procedures.

Please refer to SI B01 09 06 – Defect Code for Programming Prior to Accessory Retrofit.

Important information

The instructions below are developed for BMW vehicles and are not to be compared to any other existing instructions for vehicles other than BMW. No methods other than those specified in this document are to be used for installation in BMW vehicles. Left and right are determined from the driver's seat.

Carefully read all instructions and supplements before proceeding with the installation. Reference should be made to TIS for instructions dealing with a stock part of the vehicle but not stated in detail in these instructions.

The instructions were complete and up to date at time of publication; however, changes to the vehicle or installation may have occurred. Please report any problems or changes noted with the installation to BMW Technical Hotline, along with VIN, date of manufacture and as much detail as possible.

Do not archive the hard copy of these installation instructions since daily updates are made by ASAP.

PARTS INFORMATION


Contents of Kit – P/N 65 73 0 444 089

| Description | Qty | BMW Part Number |
|-----------------------------------|-----|-----------------|
| Bracket for hood switch | 1 | 61 31 6 932 791 |
| Mounting plate | 1 | 65 75 6 936 588 |
| Bracket for Alternate Power Siren | 1 | 65 75 6 940 124 |
| Alternate Power Siren/Tilt Sensor | 1 | 65 75 9 124 581 |
| Screw ST 4.8x13 | 1 | 07 11 9 906 163 |
| Ultrasonic Module Interior Sensor | 1 | 65 75 9 149 671 |
| Hood Switch | 1 | 61 31 9 119 052 |
| Hex Nut M6 with captive washer | 4 | 07 12 9 904 008 |
| Hex Bolt M6 with washer | 2 | 07 12 9 904 868 |

Contents


| Section | Page |
|---|------|
| 1. Interior Ultrasonic Module Installation | 4 |
| 2. Hood Switch Installation | 5 |
| 3. Alternate Power Siren/Tilt Sensor Installation | 6 |
| 4. Retrofit coding | 8 |
| 5. Personal Profile Settings | 9 |
| 6. Functional Test | 10 |

1. Interior Ultrasonic Module Installation



1.1
Disconnect negative battery terminal.

1.2
Remove ceiling light cover (1) from ceiling light housing (2) using Special Tool 00 9 341.
Refer to TIS 63 31 004.




1.3
Install ultrasonic module (1) into ceiling light as shown.

1.4
Connect 8-position black connector (2) to ultrasonic module (1).


1.5
Reinstall ceiling light cover to headliner.

2. Hood Switch Installation



2.1


Locate 3-position black hood switch connector (1). Remove securing tape and protective cover.



Note: Make sure "corner notch" on bracket faces rearward and fits into base mounting tab as shown.

2.2

Position hood switch bracket (2) to mounting location (1) and secure in place with ST 4.8 x 13 screw (3).




2.3

Insert hood switch (1) into hood switch bracket (2).

2.4

Connect hood switch connector (3) to hood switch (2).


3. Alternate Power Siren/Tilt Sensor Installation




3.1
Remove LH rear wheel.

3.2
Remove LH rear wheel arch cover.
Refer to TIS 51 71 041

3.3
Locate 3-position black siren connector (1) in upper LH wheel arch area. Remove securing tape and protective cover.




3.4
Install siren bracket (1) over threaded studs and secure in place with three M6 hex nuts (2).




3.5
Position siren (2) to mounting plate (3) and secure in place with M6 hex nut (1).

3. Alternate Power Siren/Tilt Sensor Installation



3.6
Connect 3-position black connector (1) to siren (2).

3.7
Push harness retainer into access hole on siren bracket to keep harness properly positioned.



3.8
Use M6x18 hex bolts (1) to secure mounting plate (2) to bracket (3).

3.9
Reinstall LH rear wheel arch cover.

3.10
Reinstall LH wheel.

Installation complete.

Please complete retrofit coding procedures on the next page.

4. Retrofit coding

Note: Please refer to SI B09 05 01 for latest Progman retrofit procedure before starting vehicle coding.

Reconnect negative battery terminal.

Retrofit DWA (alarm system) using Progman CIP 27.2 or later .

Follow approved Progman Retrofit procedures until Retrofit selection appears then:

Program session

Program selection:

- **Select "Load SW"**

Have control modules been replaced on this car?

- **Select "No"**

Screen will appear stating "Fitted control modules are being determined, followed by Select control module to be processed"

- **Select "Retrofits"**

Screen will appear stating "Selecting Retrofits"

- **Select "Retrofits"**

Screen will appear stating "Retrofits have been added"

- **Select "DWA"**

Screen will appear stating "Select sub function for retrofits or cancel with arrow in navigational column

- **Select "Added"**

Screen will appear stating "Retrofitting Antitheft alarm system selected

- **Select "Continue"**

Screen will appear stating "The voltage is being tested; vehicle context is being checked again" followed by "Measures plan is being determined"

Screen will appear stating "A measures plan has been created and accepted. It takes 1 minute to execute this measures plan"

- **Select "Start"**

Screen will appear stating "The CKM values are being saved"; "The GM control module _____"; "The CKM values are being restored"

Final Report

- **Select "Finish"**

To determine if DWA code number K302 is in vehicle order (VO)

- **Select "Change"**
- **Select "Vehicle"**
- **Select "Complete encoding"**

Screen will appear stating "You start coding the entire vehicle with the following functions

- **Select "Continue"**

Screen will appear stating "Should coding of the entire car be started now?"

- **Select "Yes"**

Screen will appear stating "Measures Plan is being determined"

Screen option will appear showing Measures Plan, DWA option code number K302 should be the last number listed in the vehicle order.

- **Select "Print"** if a printed copy of measures plan is desired.
- **Select "End"** **NOTE: DO NOT SELECT ACCEPT**

Upon completion of anti-theft alarm system coding, conduct alarm system test to verify functionality of alarm system.

5. Personal Profile Settings

Personal Profile Settings allow the customer to modify select settings for the Alarm system.

For vehicles with optional Navigation (SA 609):

- Settings can be selected via iDrive menu.
Please refer customer to Vehicle Owner's Manual "Personal Profiles" and "Alarm" sections for more information.

For vehicles without Navigation:

- The visual and audio confirmation settings can be modified via the Settings and Information on the Instrument Cluster using the left hand stalk.
- All settings are set to active by default.
Please refer customer to Vehicle Owner's Manual "Alarm System" and "Settings and Information" sections for more information.

6. Functional Test

Upon completion of retrofit coding, verify that alarm system is working correctly by going through the following action and response steps in order listed to ensure alarm system is functioning properly.

| Action | Response |
|--|--|
| <p>Lock vehicle and arm alarm system with remote key by pressing the round "Roundel" button on remote key.</p> <p>Vehicle is locked and alarm system armed but alarm status LED flashes rapidly for about 20 times, then flashes normally at 3 second intervals.</p> | <p>All doors, hood and trunk lock at same time. Alarm status LED on rearview mirror will start flashing approximately once every 3 seconds indicating properly functioning alarm system.</p> <p>This indicates a secure point (i.e. a door, the trunk or hood) is not secure or interior sensor is not properly connected. Locate and correct cause of secure point fault and retry locking vehicle and arming alarm system with remote key.</p> |
| <p>Check functionality of hood switch.</p> <p>Lock vehicle and arm alarm system with remote key.</p> <p>Push down on hood switch contact point.</p> <p>If alarm siren fails to sound, verify siren/tilt sensor is properly connected and repeat above procedure.</p> | <p>Open vehicle hood. Pull up on hood switch contact point to place hood switch in "test mode". This action simulates that hood is closed to alarm control module while vehicle hood is physically open.</p> <p>Verify that alarm status LED on rearview mirror is flashing normally at 3 second intervals.</p> <p>This task should result in alarm siren sounding! Press "arrow" button on remote key to disarm alarm.</p> |
| <p>Unlock vehicle and disarm alarm system with remote key. Close vehicle hood. Open driver's door and sit in driver's seat. Place key in ignition. Open all door windows. Exit vehicle and close driver's door.</p> <p>Verify that all doors, hood and trunk are closed and secure.</p> <p>Lock vehicle and arm alarm system with remote key.</p> <p>Wait about 2 minutes for interior sensor to fully recognize interior parameters of vehicle.</p> <p>Pass your arm through driver's door open window towards center console area in an attempt to activate alarm interior sensor.</p> | <p>All doors, hood and trunk lock at same time and interior sensor is activated. Alarm status LED on rearview mirror will start flashing approximately once every 3 seconds indicating properly functioning alarm system.</p> <p>This task should result with alarm siren sounding! Press "arrow" button on remote key to disarm alarm.</p> |

6. Functional Test

| Action | Response |
|---|--|
| <p>Check functionality of tilt sensor.</p> | <p>Close all doors, hood and trunk.</p> |
| <p>Lock vehicle and arm alarm system with remote key.</p> | <p>Verify that alarm status LED on rearview mirror is flashing normally at 3 second intervals.</p> |
| <p>Place a floor jack under any one of the four lift points. Begin jacking vehicle up.</p> | <p>This task should result with alarm siren sounding! Press "arrow" button on remote key to disarm alarm.</p> |
| <p>Alarm status LED on rearview mirror flashes once every 3 seconds indication properly functioning alarm system, but alarm siren will not sound when passing your arm through driver's door open window towards center console area in an attempt to activate alarm interior sensor.</p> | <p>Contact BMW Technical Hotline stating problem. It may be necessary for a modified vehicle order file be sent to you for loading into the vehicle's vehicle order to initiate proper function of alarm system.</p> |
| <p>A modified vehicle order has been installed.</p> | <p>Verify that alarm system is working correctly by going through the above action and response steps.</p> |